





TruTool TKF 700 (2A1)

订货号 备件			
No. D'ORDINE	PEZZO DI RICAMBIO		
NO. DE REF.	PIEZA DE RECAMBIO		
NO. DE REF.	PIECE DE RECHANGE		
ORDER NO.	SPARE PART		
NO BEST.-NR.	ERSATZTEIL		
1	2478862	17	0132371 2x Standard (incl. 1x Pos 16)
2	0963618		0132740 2x Cr (incl. 1x Pos 16)
3	0751869	18	0130878
4	0359353	19	2372588 D 230V 50/60Hz
5	0094676		2372589 CH 230V 50/60Hz
6	0993851		2372590 GB 110V 50Hz
7	0085111		2372641 USA 120V 50/60Hz
8	0094667		2372642 KR 220V 60Hz
9	2476397		2372643 CN 220V 50Hz
10	0094666	20	1951628
11	0131062	21	1893473 D 230V 50/60Hz
12	0094676		1893473 CH 230V 50/60Hz
13	0131182		1893474 GB 110V 50Hz
14	0093539		1893475 USA 120V 50/60Hz
15	0113038		1893476 KR 220V 60Hz
16	0131188		2007322 CN 220V 50Hz
		22	0977770 30°
			0977769 37.5°
			0977767 45°




45°

122	0134671		133	0140807	
123	0109924		134	0131063	
124	0127987		135	0130871	
125	0130869		136	0131216	
126	0130881		137	0977768	
127	0132728		138	0375702	
128	0131214		139	0131183	
129	0130882		140	0131061	
130	0131217		141	0131217	
131	0977765		142	0130868	
132	2476471				



37.5°

122	0134671		133	0140807	
123	0109924		134	0131063	
124	0127987		135	0130871	
125	0130869		136	0131216	
126	0130881		237	0259380	
127	0132728		138	0375702	
128	0131214		139	0131183	
129	0130882		140	0131061	
130	0131217		141	0131217	
231	0259379		142	0130868	
232	2476473				



30°

122	0134671		133	0140807	
123	0109924		134	0131063	
124	0127987		135	0130871	
125	0130869		136	0131216	
126	0130881		337	0134607	
127	0132728		138	0375702	
128	0131214		139	0131183	
129	0130882		140	0131061	
130	0131217		141	0131217	
331	0134609		142	0130868	
332	2476400				

