German Automotive Tool Innovator



GLOW PLUG DRILL KIT - M10X1.25











Remove broken glow plugs effectively and safely in 5 easy steps

- 1. Break the electrode by turning counter clockwise with socket;
- 2. Drill pitch away with special 3 fluted step drill;
- 3. Tap the left thread inside the remaining glowplug piece;
- 4. Extract the last pitches with thread tap and clean up the hole;
- 5. Remove remaining portion of glow plug with extractor and slide hammer.

Set comes in a metal box with a straightforward picture manual.

www.mueller-kueps.com